

Nepshaw Lane South, Morley, Leeds, LS₂₇7JQ Materials Testing Manager: Martin Bowden

t: 0113 5350176

e: Materials.Testing@wyjs.org.uk www.wyjs.org.uk/materialstesting



TEST REPORT

Client: Gabriel

Hjulmagervej 55 Postbox 59 DK-9100 Aalborg

Denmark

Entry No: 109720

Date received: 22/05/2019

Client's Description: Fabric Sample Passion 1101

Test Required: Abrasion in accordance with BS EN 14465 and BS 2543: 2004

Conditioning: In accordance with BS EN ISO 139: 2005 for a minimum of 24 hours at

65+/-4%, Relative Humidity, 20+/-2°C

Date Tests Completed: 17/06/2019

Abrasion Resistance: BS EN ISO 12947-2: 2016F

The tests were carried out using a pressure of 12 +/- 0.3 kPa The criterion for judging end point was three threads broken

The Test was terminated after 200,000 rubs without an end point having been reached.

Change in colour after 6,000 rubs:

Observation Technique: 10 fold magnification

Type of Fabric: Flat Woven

-----End of Document------

This is hereby certified to be a correct return of the tests made of the items referred to herein

Claire Saville Technologist 18th June 2019

- Unless instructed otherwise by the client sample remnants will be disposed of after 28 days.
- Tests marked ^N in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory.
 Tests marked ^F in this certificate are performed under the Laboratory's Flexible Scope of Accreditation.
- Tests marked in this certificate have been subcontracted to another ISO17025 Accredited Laboratory.
- Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.
- Uncertainty budgets for test methods contained within this report are available on request.

This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.



