

Nepshaw Lane South, Morley, Leeds, LS27 7JQ Materials Testing Manager: D. J. Brockbank t: 0113 393 9791 e: dale.brockbank@wyjs.org.uk www.wyjs.org.uk/materialstesting



TEST REPORT

Client:	Gabriel Hjulmagervej 55 Postbox 59 DK-9100 Aalborg, Denmark	
Entry No:	82185-01	
Date received:	03/01/2017	
Client's Description:	Sample of fabric: Comfort+/Beige	
Test Required:	Dimensional Stability to Washing	
Conditioning:	In accordance with BS EN ISO 139: 2005 for a minimum of 24 hours at 65+/-4%, Relative Humidity, 20+/-2°C	
Date Tests Completed:	17/01/2017	
Dimensional Stability: BS EN ISO 5077: 2008 Washing Procedure: BS EN ISO 6330: 2004 Procedure 3A (74°C), Drying Procedure C Flat dry		
Note: a negative result indica	Length Width ates shrinkage.	-1.5 % -2.5 %

-----End of Document-----

This is hereby certified to be a correct return of the tests made of the items referred to herein

Vivienne Brockbank Technician 29 January 2017

Unless instructed otherwise by the client sample remnants will be disposed of after 28 days. \*

Tests marked <sup>N</sup> in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory. Tests marked <sup>F</sup> in this certificate are performed under the Laboratory's Flexible Scope of Accreditation. Tests marked <sup>S</sup> in this certificate have been subcontracted to another ISO17025 Accredited Laboratory. ÷

÷

- ٠ Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.
- Uncertainty budgets for test methods contained within this report are available on request.

This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.



